

## 16032002 N Q

CORNER HISTORY: A survey by Wm. B. Laughlin dated 1820 called witness: 12" beech N 33 W 36 links; 8" buckeye S 32 E 1 link per Marion County Atlas pg. 6. Old Tie card dated 6-29-1964 called spike in pipe was found. Old tie card (no date) called a  $1\frac{1}{2}$ " pipe. Old tie card dated 4-23-70 called this corner a brass plug in concrete. Survey by Scherschel called corner a rebar dated 9-1978. Reference dated 6-22-02 by Wilcoxen called found 30" long rebar. Set Harrison where the rebar was found. No stone found.

ounou	, odna oo i	ong result. Ser riarrison where the result was regula. No stone round.
REF.	DISTANCE	DESCRIPTION
1.	69.78'	Cut 'x' NW corner of concrete wall of bridge wall
2.	9.1'	W to face of bridge wall
3.	12.03'	Cut 'x' NF corner bridge wall
4.	73.28'	Mag nail w/bw F railroad tie of railroad track